

**Fiat Punto**
Emotion 90HP

Car Details

Brand	Fiat
Year of Manufacture	2013
Manufacture Date	Jul/2013
City	Bangalore
Fuel Type	Diesel
Transmission	Manual
Registration Number	KA03MM0000
KMS Driven	64657 km
No Of Owner's	2
Road Tax Paid	Life Time
Road Tax Validity	Sep/2028
Insurance Type	Comprehensive
Insurance Validity	31/10/2026
Current RTO	East
Car Length	4-5 meters
Cubic Capacity	1248
No Of Keys	2
Reg Date	Sep/2013

Car Images



Front



Front Right



Right Side



Rear Right



Rear Left



Left Side



Front Left



Rear



Front Seats



Steering and Instrument Cluster



Driver Footwell



Rear Seats



Center Console Gear Infotainment



Roof Lining



DashBoard



Keys and Remote



Rear Boot Open




Engine Bay



Chassis Numer Vin Plate

Summary



Interior

Part	Status	Reason	Comment
Starter Motor Condition ?	Ok		
Odometer Reading	64657		
Power Window ?	Yes		
AC ?	Ok		
AC Vents Condition?	Not ok	Broken or Missing Co Driver Side	
Air Bags ?	Ok		
LH : Outside rearview mirror operation and switches condition	Ok		
Right : Outside rearview mirror operation and switches condition	Ok		
Inside rearview mirror condition	Ok		
Music system	Ok		
Music system - Touch Screen	Yes	No Navigation	
Instrument cluster photo with no warning lights	Ok		
Driver Seat condition	Ok		
Co driver Seat Condition	Ok		
Rear Passengers Seat Condition	Ok		

Part	Status	Reason	Comment
last Row Passenger Seat Condition	N/A		
Dash board	Ok		
Door Pads - Dicky door	Ok		
Roof Lining	Ok		
Flood exposure	Ok		
Key Condition	Ok		
Roof Lights	Ok		
RH Door Pad & Controls	Ok		
LH Door Pads & Controls	Ok		
Rear RH Door Pad & Controls	Ok		
RearLH Door Pads & Controls	Ok		
Release Levers/Knobs(Fuel lid & Trunk)	Ok		

Exterior/Front

Part	Status	Reason	Comment
Front bumper	Not ok	Part Repaired,Repainted good quality	
Radiator grill	Ok		
LH: Head Lights	Not ok	Broken clamps,Feaded	
RH: Head Lights	Not ok	Feaded	
LH: Fog Lamps	Ok		
RH: Fog Lamps	Ok		
Bonnet Hood	Not ok	Repainted good quality,Major or Multiple Dents,multipe minor scratches	
Front Windshield	Ok		
Roof	Not ok	Repainted good quality,Major or Multiple Dents,multipe minor scratches	
Uderchassis Front	Ok		
Upper cross member/bonned putti	Ok		
Lower cross memeber	Ok		
Right apron	Ok		
LH apron	Ok		
Right lower apron	Ok		
LH lower apron	Ok		
Antena	Ok		
Roof	Ok		
Cowl Top	Ok		
Firewall	Ok		
Floor Panel	Ok		

Exterior/Right

Part	Status	Reason	Comment
RH Indicator Turn Signal	Ok		
RH Fender	Ok		
RH Rear View Mirror	Ok		
RH Front Door	Not ok	Repainted good quality,Minor scratches	
RH Running Board	Not ok	Part Repaired,Repainted good quality	
RH Rear Door	Not ok	Repainted good quality	
RH Quarter Panel	Not ok	Part Repaired,Major or Multiple Scratches,Minor scratches	
RH Rear Tyre	Ok		
RH A Piller	Ok		
RH B Piller	Ok		
RH C Piller	Ok		
RH Front tyre	Ok		

Exterior/Back

Part	Status	Reason	Comment
RH Tail Light	Ok		
Rear Windshield	Ok		
Trunk Tail Gate	Not ok	Part Repaired,Repainted good quality,Major or Multiple Dents	Dicky lifter needs replacement
Spare wheel	Not ok		Need replacement
Tool Kit, Jack, Handle	Ok		
Tail Light LH	Ok		
Rear bumper	Not ok	Part Repaired,Repainted good quality,Minor scratches	
RH Tail skrut	Ok		
Dicky floor	Ok		
Dicky floor back pannel	Ok		
LH Tail Skurt	Ok		
Reverse Camera	N/A		
Underchassis Rear	Ok		

Under the hood

Part	Status	Reason	Comment
Coolant Level & Reservoir	Level Ok		
All Drive Belts Condition	Ok		
Brake fluid	Level ok		
Batter make & year	Ok		

Part	Status	Reason	Comment
Power Steering Fluid(If hydraulics)	Level ok		
Electrical Wiring	Ok		
Fuses & Relays	Ok		
Air Filter Housing	Ok		
Radiator Hoses	Ok		
Vacuum & Fuel Hoses	Ok		
Engine Oil & level	Not Ok	Black color	
Fluid Leaks in Engine & other Systems	No Leak		
Exhaust Manifold	Ok		

Road Test

Part	Status	Reason	Comment
Engine condition	Ok		
Engine Compression	Ok		
Accelerator condition	Ok		
Clutch Condition	Ok		
Gear box condition	Ok		
Drive shaft condition	Ok		
Suspension	Ok		
Dash board noise	Ok		
Wiper Front	Not ok	Wiper blades need replacement	no wiper blade
Wiper Rear	Not ok	Noisy	no wiper blade
ECM	Ok		
Engine blow by	No now by		
Engine smoke	Normal Smoke		
Odometer photo after test drive	64658		
Brake	Ok		
Steering	Ok		
Engine Start	Ok		
Silencer	Ok		

Exterior/Left

Part	Status	Reason	Comment
LH Indicator Turn Signal	Ok		
LH Quarter Panel	Not ok	Repainted good quality	
LH Rear Tyre	Not ok	Tyre Need Replacment	
LH Rear Door	Not ok	Repainted Bad Quality	
LH Running Board	Ok		
LH Front Door	Not ok	Repainted good quality, Major or Multiple Dents	


Part	Status	Reason	Comment
LH Rear View Mirror	Ok		
LH Fender	Not ok	Major or Multiple Scratches	
LH Front Tyre	Ok		
LH C Pillar	Ok		
LH B Pillar	Ok		
LH A Pillar	Ok		

Special Features

Part	Status	Reason	Comment
Speciacl Features	Yes		

Defects

Engine Oil & level



Black color

All Drive Belts Condition



Batter make & year



LH: Head Lights



Broken clamps,Feaded

RH: Head Lights



Feaded

RH: Fog Lamps



Front bumper



Part Repaired,Repainted good quality

Bonnet Hood



Repainted good quality,Major or Multiple Dents,multiple minor scratches

Bonnet Hood



Repainted good quality,Major or Multiple Dents,multiple minor scratches

Roof



Repainted good quality,Major or Multiple Dents,multiple minor scratches

Uderchassis Front



RH Front Door



Repainted good quality, Minor scratches

RH Front Door



Repainted good quality, Minor scratches

RH Running Board



Part Repaired, Repainted good quality

RH Rear Door



Repainted good quality

RH Front tyre



RH Rear Tyre



RH Quarter Panel



Part Repaired, Major or Multiple Scratches, Minor scratches

RH Quarter Panel



Part Repaired, Major or Multiple Scratches, Minor scratches

Trunk Tail Gate



Part Repaired, Repainted good quality, Major or Multiple Dents

Dicky lifter needs replacement

Trunk Tail Gate



Part Repaired, Repainted good quality, Major or Multiple Dents

Dicky lifter needs replacement

Rear bumper



Part Repaired, Repainted good quality, Minor scratches

Spare wheel



Need replacement

Underchassis Rear



LH Quarter Panel



Repainted good quality

LH Rear Door



Repainted Bad Quality

LH Front Door



Repainted good quality, Major or Multiple Dents

LH Fender



Major or Multiple Scratches

LH Front Tyre



LH Rear Tyre



Tyre Need Replacment

Wiper Rear



Noisy

no wiper blade

Wiper Front



Wiper blads need replacement

no wiper blade

AC Vents Condition?



Broken or Missing Co Driver Side

AC Vents Condition?



Broken or Missing Co Driver Side

LH : Outside rearview mirror operation and switches condition



Music system - Touch Screen



No Navigation

Instrument cluster photo with no warning lights



Odometer Reading

